


TBS



SILART
8 800 555 09 66
E-mail: info@silart.com
Web: www.silart.com



3.	TBS-140	TBS-240	TBS-160	TBS-260
	NC	NO	NC	NO
	-20...+40 °C		0...+60 °C	
	7±3 °C			
	±4 °C			
	250VAC / 16 (cos =0,95)			
	72VDC / 30			
	AC/DC 10 / 5			
	1500			
	50			
	10			
	-20...+80 °C			
	100000			
	IP20			
	UL94 V-0			
	RAL7035			
	0,35...2,5 ²			
	* 0,35...1,5 ²			
	2,5 . 0,4			
	36			

5.
$T = 5^{\circ}\text{C} + (7+3)^{\circ}\text{C} + 4^{\circ}\text{C} = 19^{\circ}\text{C}$
$T = 20^{\circ}\text{C} + (7+3)^{\circ}\text{C} + 4^{\circ}\text{C} = 34^{\circ}\text{C}$
5...10°C.

1.

• NC ():
• NO ():

2.

TBS
• NC ():
• NO ():

4.

• 35 DIN -
• (. . 1);
• 5
• 3.
• 14 ;
• 3
• 4-

